

ENSR

PHOTOGRAPHIC LOG



Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	Project No. 01855-061
Photo No. 1	Date: 5/28/08		
Direction Photo Taken: Aerial view looking north			
Description: Site overview showing temporary sheeting in water, perimeter controls, barge mounted excavator performing dredging, transport barges, and land based excavator used for load-out. (Phase 1)			

Photo No. 2	Date: 6/23/08	
Direction Photo Taken: Looking west – from across the creek.		
Description: Site overview from across the creek. (Phase 1)		

ENSR		PHOTOGRAPHIC LOG	
Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	
		Project No. 01855-061	
Photo No. 3	Date: 4/22/08		
Direction Photo Taken: Looking East			
Description: Installation of permanent steel sheet pile wall (replacement bulkhead) on Todd Seafood property. (Phase 1)			
Photo No. 4	Date: 5/1/08		
Direction Photo Taken: Looking southeast			
Description: Installation of temporary sheeting around NAPL area in Cambridge Creek. (Phase 1)			

<div>ENSR</div>		<div>PHOTOGRAPHIC LOG</div>	
<div>Client Name:</div> <div>Delmarva Power & Light Co.</div>		<div>Site Location:</div> <div>Cambridge, MD</div>	
		<div>Project No.</div> <div>01855-061</div>	
<div>Photo No.</div> <div>5</div>	<div>Date:</div> <div>5/14/08</div>		
<div>Direction Photo Taken:</div> <div>Looking east</div>			
<div>Description:</div> <div>Dredge bucket with sediment.</div> <div>(Phase 1)</div>			

<div>Photo No.</div> <div>6</div>	<div>Date:</div> <div>5/14/08</div>		
<div>Direction Photo Taken:</div> <div>Looking northeast</div>			
<div>Description:</div> <div>Placement of dredged sediment in transport barges.</div> <div>(Phase 1)</div>			

ENSR

PHOTOGRAPHIC LOG

Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	Project No. 01855-061
Photo No. 7	Date: 5/14/08		
Direction Photo Taken: Looking north			
Description: Sediment load-out from transport barges into trucks. (Phase 1)			

Photo No. 8	Date: 6/23/08	
Direction Photo Taken: Looking northeast		
Description: Sand backfilling (Phase 1)		

ENSR

PHOTOGRAPHIC LOG

Client Name:
Delmarva Power & Light Co.

Site Location: Cambridge, MD

Project No.
01855-061

Photo No.
9

Date:
6/23/08 &
8/1/08

Direction Photo Taken:

Looking north

Description:

- 1) Dock replacement in progress. New replacement bulkhead on the landside of the dock.

- 2) Dock replaced.
Bulkhead capped.

(Phase 1/ Phase 2)



Photo No.
10

Date:
7/28/08

Direction Photo Taken:

Looking southeast

Description:

Air Monitoring Station #3
with PID and Particulate
Monitor.

(Phase 1 and Phase 2)



ENSR

PHOTOGRAPHIC LOG

Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	Project No. 01855-062
Photo No. 13	Date: 7/17/08		
Direction Photo Taken: Looking northeast and downward			
Description: Excavation within gas holder in the northwest corner of DPL property. (Phase 2)			

Photo No. 14	Date: 7/17/08	
Direction Photo Taken: Looking east		
Description: Odor suppressant foam on excavated impacted soils. (Phase 2)		

ENSR

PHOTOGRAPHIC LOG

Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	Project No. 01855-062
Photo No. 15	Date: 7/21/08		
Direction Photo Taken: Looking east			
Description: Excavation of impacted soils from Delmarva property. (Phase 2)			

Photo No. 16	Date: 7/23/08	
Direction Photo Taken: Looking southwest		
Description: Backfilling and compaction. (Phase 2)		

ENSR

PHOTOGRAPHIC LOG

Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	Project No. 01855-062
Photo No. 15	Date: 7/17/08		
Direction Photo Taken: Looking southeast			
Description: Underground storage tank removal FROM Todd's Seafood property. (Phase 2)			

Photo No. 16	Date: 7/24/08	
Direction Photo Taken: Looking west/southwest		
Description: Replacement of city storm drain (Phase 2)		

ENSR

PHOTOGRAPHIC LOG


Client Name: Delmarva Power & Light Co.		Site Location: Cambridge, MD	Project No. 01855-062
Photo No. 17	Date: 8/1/08		
Direction Photo Taken: Looking east			
Description: Compaction testing by John D. Hynes & Associates (Phase 2)			

Photo No. 18	Date: 8/14/08	
Direction Photo Taken: Looking northeast		
Description: Installation of Final Cap (Phase 2)		

<div>ENSR</div>		<div>PHOTOGRAPHIC LOG</div>	
<div>Client Name:</div> <div>Delmarva Power & Light Co.</div>		<div>Site Location:</div> <div>Cambridge, MD</div>	
<div>Project No.</div> <div>01855-062</div>			
<div>Photo No.</div> <div>19</div>	<div>Date:</div> <div>8/13/08</div>		
<div>Direction Photo Taken:</div> <div>Aerial view looking north</div>			
<div>Description:</div> <div>Restored site with all equipment demobilized.</div> <div>(Phase 1 and 2)</div>			

<div>Photo No.</div> <div>20</div>	<div>Date:</div> <div>8/17/08</div>	
<div>Direction Photo Taken:</div> <div>Looking north</div>		
<div>Description:</div> <div>Hydroseeded area</div> <div>(Phase 1 and 2)</div>		